FIRMWARE UPDATE PROCEDURE FOR **HBCS1D10U Rev. 2.0** READER

WARNING: the update in question must be performed only on the **REV 2.0** version of the **HBCS1D10U** device.

Before proceeding, verify that **REV 2.0** is shown on the label containing the code and serial number on the device. Updating a different REV model could damage and make the device unusable.


After running the update file named **S104 V1.07 MSI XB 20240627.exe**, follow the instructions below.

IMPORTANT: DO NOT connect the **HBCS1D10U** device to the computer at this time.

1. Select English language.



2. Press START.



3. Hold the trigger button of HBCS1D10U reader and connect the device to USB port of the computer.
4. Wait a few seconds until the update is complete.